

Section 19 (Figure 19.1)
Case 1 : Water Table at RL +0.8m with long term parameters

Material #: 1	Material #: 2	Material #: 3
Description: Silty Sand	Description: Silty Clay	Description: Water
Wt: 18	Wt: 17	Wt: 9.807
Cohesion: 5	Cohesion: 2	
Phi: 25	Phi: 25	

