

Section 19 (Figure 19.2)
Case 2 : Water Table at RL +5.1m with short term parameters

Material #: 1	Material #: 2	Material #: 3
Description: Silty Sand	Description: Silty Clay	Description: Water
Wt: 18	Wt: 17	Wt: 9.807
Cohesion: 12	Cohesion: 15	
Phi: 0	Phi: 0	

