

Section 8 (Figure 8.2)
Case 2 : Water Table at RL +4.3m with Short Term parameters

Material #: 1	Material #: 2
Description: Silty Sand	Description: Silty Clay
Wt: 18	Wt: 17
Cohesion: 12	Cohesion: 15
Phi: 0	Phi: 0
	Material #: 3
	Description: Water
	Wt: 9.807

